



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

### Minerals Regulatory Program

Report Date

Supervisor 10074

**Mine Name:** Coyote Knoll 1-2-3

**Operator Name:**

Sid Hullinger

8960 N Hwy 40

Lakepoint, UT 84074

**Inspector(s):** Tom Munson

**Other Participants:** none

**Mine Status:** active

**Permit number:** S/023/086

**Inspection Date:** 05/4/2006

**Time:** 12:30 pm

**Weather:** sunny

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)
8. Water Impoundments
9. Soils
10. Revegetation
11. Air Quality
12. Other

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

To perform an annual inspection.

#### Inspection Summary:

The site has been mined in the last year but was inactive at the time of inspection. There is a pit and a stockpile of ore or overburden. No equipment was found on site.

#### Conclusions and Recommendations:

The site is in good shape and needs no maintenance to remain in compliance.

**Inspector's Signature** Thomas Munson

**Date:** 6/16/06

#### Directions to Site:

The site is southwest of the desert mountains west of the Delta power plant.

tm:jb

cc: McFarland & Hullinger  
BLM-Fillmore-Jerry Mansfield

O:\M023-Juab\S0230086-CoyoteKnoll\inspections\inspection061306.doc



S/023/066

COYOTE KNOLL 1-2-3



PIT





ORE ON OVER BURDEN OF IT







- well?



OVERBROWN PILE ✓

